

ELECTROMAGNETIC FLOWMETER HFM100

HFM100 ELECTROMAGNETIC FLOWMETER USER MANUAL



HIGHJOIN

Nanjing Hangjia Electronic Technology Co., Ltd.

Address: No.18, Fenghua Road, Yuhua Zone, Nanjing, Jiangsu, China

Web: www.hjsensor.com E-mail: info@hjsensor.com

HFM100 Electromagnetic Flowmeter

0\/ED\/JE\A

CATALOGUE

OVERVIEW
Instrument features and usage ······
Application ·····
Working principle ······
TECHNICAL SPECIFICATIONS
Sensor part technical parameters · · · · · · · · · · · · · · · · · · ·
Lining materials selection guide
Electrode materials selection guide·····
Measuring range
PRODUCT DIMENSIONS AND INSTALLATION DIMENSIONS
Converter dimensions
Sensor installation dimensions (reference flange standard JB/T81-1994)·····
Plug-in electromagnetic part······
PRODUCT INSTALLATION
Precautions 1
Grounding of flowmeter and pipeline
Electrical wiring
-
CONVERTOR MENUS AND SETTINGS
Display interface and button functions
Parameter setting menu list
Detailed description of parameters
Troubleshooting
Lightning protection function description 22
Lightning protection function description
ORDERING GUIDE22
TRANSPORTATION AND STORAGE23
OPERATION23
GUARANTEE AND REPAIR23

Overview

Instrument features and usage

- Measurement is not affected by changes in fluid density, viscosity, temperature, pressure and electrical rate.
- There are no flow-blocking parts in the measuring pipe, no pressure loss, low straight pipe section requirements, and unique adaptability to slurry measurement.
- Nominal diameter DN6-DN3000 covers a wide range, with multiple options for linings and electrodes, and can be applied to a variety of measurement media. Has good corrosion resistance and wear resistance.
- The converter uses programmable frequency low-frequency rectangular wave excitation, which improves the stability of flow measurement and reduces power loss.
- The converter uses a 32-bit embedded microprocessor with full digital processing, fast operation speed, strong anti-interference ability, reliable measurement, high accuracy, and the flow measurement range can reach 1500:1. The range can be modified online according to the actual needs of the user.
- High-definition backlit LCD display, Chinese and English menu operations are optional, easy to use, simple to operate, easy to learn and understand.
- With digital communication signal outputs such as RS485, RS232, Hart and Profibus (optional).
- With conductivity measurement function, it can determine whether the sensor is empty, and has self-test and self-diagnosis functions.
- Using SMD devices and surface mounting (SMT) technology, the circuit has high reliability.
- Infrared handheld communicator operation, 115KHZ communication rate, long-distance non-contact operation of all functions of the converter (optional).
- There are three internal meters that can respectively display the forward totalizer, reverse totalizer, and difference totalizer. clock, can record power-off time (optional).
- Explosion-proof optional, explosion-proof mark: Ex db ia q IIC T6 Gb / Ex tb IIIC T80°C Db.

Application

Electromagnetic flowmeters can be used to measure the volume flow of conductive fluids in closed pipelines. They can also be used to measure the volume flow of corrosive liquids such as strong acids and alkalis, and uniform liquid-solid mixed liquids such as mud, mineral slurry, and paper pulp. It is widely used in flow measurement and control in industrial and agricultural production processes such as petrochemical industry, iron and steel metallurgy, water supply and drainage, water conservancy irrigation, water treatment, environmental sewage measurement and control, papermaking, medicine, food, etc.

Working principle

The working principle of the electromagnetic flowmeter is based on Faraday's law of electromagnetic induction, as shown in Figure 1. When a conductor moves in a magnetic field, an induced electromotive force (E) will be generated at both ends of the conductor in a direction perpendicular to the direction of the magnetic field and the direction of movement. This induced electromotive force is detected by two measuring electrodes, and its value depends on the flow rate and magnetic field. is proportional to the magnetic induction intensity, its value is: E= B.V.D.K In the formula: K - coefficient related to magnetic field distribution and axial length

B-magnetic induction intensity

V-average flow rate of conductive liquid

D- electrode distance (measuring tube inner diameter)

Electrode

Voltage

Magnetic flux density (B)


The working principle of the insertion electromagnetic flowmeter is the same as that of the pipeline electromagnetic flowmeter, which is also based on Faraday's law of electromagnetic induction, as shown in Figure 2. When the conductive liquid passes through two electrodes with L at an average flow velocity V and perpendicular to the direction of the magnetic field lines with a magnetic field strength of B, A corresponding induced electromotive force (E) is generated between the electrodes, and its formula is: $E=B\times L\times V$

In the formula: B: Magnetic induction intensity of excitation coil


V: average flow velocity

L: distance between two electrodes (this machine is 24mm)

Qv: measured fluid volume flow rate



The electromagnetic flowmeter converter provides a stable excitation current to the electromagnetic flow sensor excitation coil. The preamplifier amplifies and converts the electromotive force induced by the sensor into a standard current signal or frequency signal to facilitate flow display, control, and adjustment. Figure below shows the converter circuit structure.



Technical Specifications

Sensor part technical parameters

- Measurement medium: water, acid, alkali, seawater, and other conductive liquids that are highly corrosive or contain impurities.
- Medium conductivity: ≥20uS/cm;
- Nominal diameter: DN6-DN3000mm
- Execution standards and calibration basis: JB/T9248-1999, JJG1033-2007
- Lining material: polychloroprene, polytetrafluoroethylene, silicone fluorine rubber, polyurethane rubber, F46, PFA
- Electrode materials: molybdenum-containing stainless steel, Hastelloy B, Hastelloy C, titanium, tantalum, platinum alloy, tungsten carbide
- Nominal pressure: 0.6MPa-32MPa
- Accuracy level: 0.5 G, 1.0 G.
- Flow velocity range: 0.1m/s-15m/s
- Ambient temperature: converter -10°C~+60°C
- Relative temperature: 5%-95%

Lining materials selection guide

Lining material	Main performance	Application
polychloroprene (CR)	It has excellent elasticity, high tearing force and good wear resistance. Resistant to the corrosion of general low- concentration acid, alkali and salt media, but not resistant to the corrosion of oxidizing media.	1.<60℃ 2. General water, sewage, weak abrasive mud and mineral slurry
polyurethane rubber (PU)	Excellent wear resistance (equivalent to ten times that of natural rubber) Poor acid and alkali resistance Cannot be used in water mixed with organic solvents.	1.<80℃ 2. Neutral and strong abrasion slurry, coal slurry, mud, etc.
Silicone fluorine rubber (FPM)	It has excellent elasticity, high tearing force and good wear resistance. Resistant to high temperature and non-corrosive media.	1.<180°C 2. Hot water
Polytetrafluoroethylene (PTFE)	It is a material with the most stable chemical properties among plastics; it can withstand boiling hydrochloric acid, sulfuric acid, nitric acid and aqua regia, as well as concentrated alkali and various organic solvents. It is not resistant to chlorine trifluoride, high temperature oxygen trifluoride, and high flow rates. Corrosion by liquid fluorine, liquid oxygen, and ozone. 2. Poor wear resistance. 3. Poor ability to withstand negative pressure.	1.<120°C 2. Strongly corrosive media such as concentrated acid and alkali 3. sanitary media
polyperfluoroethylenepropylene (F46)	chemical properties are equivalent to PTFE the abrasion resistance of the wear resistant layer is better than that of PTFE High pressure and negative pressure resistance	1.<180°C 2. Corrosive acid and alkali salts 3. High pressure and negative pressure resistance
perfluoroalkene (PFA)	Chemical properties are equivalent to F46 Compressive and tensile strength better than F46	1.<180°C 2. Corrosive acid and alkali salts 3. High pressure and negative pressure resistance

Electrode materials selection guide

Electrode	Material Corrosion resistance
Molybdenum-containing	It is used for industrial water, domestic water, and sewage. It has weakly corrosive media
stainless steel (316L)	and can be widely used in petroleum, chemical, urea, vinylon and other industries.
calcium carbide(WC)	Used for non-corrosive, highly abrasive media, such as paper pulp, mud, ore slurry, etc.
	It has good corrosion resistance to hydrochloric acid of all concentrations below the
Hastelloy B(HB)	boiling point, and is also resistant to corrosion by non-oxidizing acids, alkalis, and non-
Hastelloy b(Hb)	oxidizing salt liquids such as sulfuric acid, phosphoric acid, hydrofluoric acid, and organic
	acids.
	It is resistant to corrosion by oxidizing acids, such as nitric acid, mixed acid or mixed
Hastallay C(HC)	media of chromic acid and sulfuric acid, and is also resistant to corrosion by oxidizing
Hastelloy C(HC)	salts such as FE+++, CU++ or other oxidizing agents. Such as corrosion by hypochlorite
	solution and seawater above normal temperature.
	It can withstand the corrosion of sea water, various chlorides and hypochlorites,
	oxidizing acids (including fuming nitric acid), organic acids, alkalis, etc., and is not
Titanium (Ti)	resistant to the corrosion of relatively pure reducing acids (such as sulfuric acid and
	hydrochloric acid). However, if the acid contains oxidizing agents (such as nitric acid,
	FE+++, CU++), the corrosion resistance will not reduce.
	It has excellent corrosion resistance, very similar to glass. In addition to hydrofluoric acid,
Tantalum (Ta)	fuming sulfuric acid and alkali, it is resistant to corrosion by almost all chemical media
	(including hydrochloric acid, nitric acid, sulfuric acid and aqua regia)
Platinum-iridium alloy (Pt)	It is suitable for almost all chemicals except aqua regia and ammonium salts.

Measuring range

	Flow rate and Flow Comparison Table										
Flow Flow rate m/s m³/h Nominal diametersDN(mm)	0.1 (minimum)	1	2	3	4	5	15 (maximum)				
6	0.01	0.1017	0.2034	0.3051	0.4068	0.5085	1.5255				
10	0.028	0.2826	0.5652	0.8478	1.1304	1.413	4.239				
15	0.064	0.6362	1.2723	1.9085	2.5447	3.1809	9.5426				
20	0.113	1.1310	2.2619	3.3929	4.5239	5.6549	16.9646				
25	0.177	1.7671	3.5343	5.3014	7.0686	8.8357	26.5072				
32	0.2894	2.8938	5.7876	8.6814	11.5752	14.469	43.407				
40	0.452	4.5239	9.0478	13.5717	18.0956	22.6195	67.8584				
50	0.707	7.0686	14.1372	21.2058	28.2743	35.3429	106.0288				
65	1.195	11.9459	23.8918	35.8377	47.7836	59.7295	179.1886				
80	1.810	18.0956	36.1911	54.2867	72.3823	90.4779	271.4336				
100	2.827	28.2743	56.5487	84.8230	113.0973	141.3717	424.1150				
125	4.416	44.1563	88.3126	132.4689	176.6252	220.7815	662.3445				
150	6.362	63.6173	127.2345	190.8518	254.4690	318.0863	954.2588				
200	11.310	113.0973	226.1947	339.2920	452.3893	565.4867	1696.4600				
250	17.671	176.7146	353.4292	530.1438	706.8583	883.5729	2650.7188				
300	25.447	254.4690	508.9380	763.4070	1017.8760	1272.3450	3817.0351				
350	34.636	346.3606	692.7212	1039.0818	1385.4424	1731.8030	5195.4089				
400	45.239	452.3893	904.7787	1357.1680	1809.5574	2261.9467	6785.8401				
450	57.256	572.5553	1145.1105	1717.6658	2290.2210	2962.7763	8588.3289				
500	70.686	706.8583	1413.7167	2120.5750	2827.4334	3534.2917	10602.8752				
600	101.788	1017.8760	2035.7520	3053.6281	4071.5041	5089.3801	15268.1403				
700	138.544	1385.4424	2770.8847	4156.3271	5541.7694	6927.2118	20781.6354				
800	180.956	1809.5574	3619.1147	5428.6721	7238.2295	9047.7868	27143.3605				
900	229.022	2290.2210	4580.4421	6870.6631	9160.8842	11451.1052	34353.3157				
1000	282.743	2827.4334	5654.8668	8482.3002	11309.7336	14137.1669	42411.5008				
1200	407.150	4071.5041	8143.0082	12214.5122	16286.0163	20357.5204	61072.5612				
1400	554.177	5541.7694	11083.5389	16625.3083	22167.0778	27708.8472	83126.5416				
1600	723.823	7238.2295	14476.4589	21714.6884	28952.9179	36191.1474	108573.4421				
1800	916.088	9160.8842	18321.7684	27482.6525	36643.5367	45804.4209	137413.2627				
2000	1130.973	11309.7336	22619.4671	33929.2007	45238.9342	56548.6678	169646.0033				


Remarks:

- 1) The flow rate range for level 0.5 guaranteed accuracy is $0.5\sim5$ m/s, and the range ratio of the corresponding flow range is 1:10
- 2) The above table lists the flow rates corresponding to several representative flow rates. The flow rate corresponding to any flow rate can also be calculated using this table: If the flow rate value Q (m3/h) is known, then find out from the table the flow value Q1 corresponding to the flow rate of 1 m/s in the corresponding diameter, then for the flow rate V=Q/Q1 (m/s)

-4-


Product Dimensions and Installation Dimensions

Converter dimensions




Sensor installation dimensions (reference flange standard JB/T81-1994)

♦ DN15-DN150, 1.6, 2.5MPA sensor and integrated outline drawing



Nominal diameters			L H	Nominal diameters		Pres	ssure 1.6	MPa			Pre:	ssure 2.51	MPa	
DN	L		DN	D	d1	d0	n	b	D.	d1	d0	n	b	
15	200	147	15	95	65	14	4	16	95	65	14	4	16	
20	200	154	20	105	75	14	4	18	105	75	14	4	18	
25	200	156	25	115	85	14	4	18	115	85	14	4	18	
32	200	166	32	135	100	18	4	18	135	100	18	4	20	
40	200	172	40	145	110	18	4	20	145	110	18	4	22	
50	200	191	50	160	125	18	4	22	160	125	18	4	24	
65	250	200	65	180	145	18	4	24	180	145	18	4	24	
80	250	218	80	195	160	18	8	24	195	160	18	8	24	
100	250	242	100	215	180	18	8	26	230	190	23	8	28	
125	250	277	125	245	210	18	8	28	270	220	26	8	30	
150	300	302	150	280	240	23	8	28	300	250	26	8	30	


♦ DN200~DN600, 1.0, 1.6MPA sensor and integrated outline drawing



Nominal diameters		1.0	Nominal diameters	F	ressur	e 1.6	MPa		F	ressur	e 1.0	MPa	
DN	L	H DN		D	d1	d0	n	b	D	d1	d0	n	b
200	350	362	200	335	295	23	12	30	335	295	23	8	24
250	450	412	250	405	355	26	12	32	390	350	23	12	26
300	500	472	300	460	410	26	12	32	440	400	23	12	28
350	500	522	350	520	470	26	16	34	500	460	23	16	28
400	500	572	400	580	525	30	16	38	565	515	26	16	30
450	550	626	450	640	585	30	20	42	614	565	26	20	30
500	550	676	500	705	650	34	20	45	680	620	26	20	32
600	600	776	600	840	770	41	20	50	780	725	30	20	36

-6-


◆DN700-DN2000, 0.6, 1.0MPA sensor outline drawing



Nominal diameters DN	L	Н
700	700	866
800	800	966
900	900	1076
1000	1000	1200
1200	1200	1406
1400	1400	1632
1600	1600	1832
1800	1800	2036
2000	2000	2236

Nominal diameters DN	Pressure(Mpa)	D	d1	d0	n	b
700		895	840	30	24	36
800	1.0	1010	950	34	24	38
900	1.0	1110	1050	34	28	42
1000		1220	1160	36	28	44
700		860	810	25	24	32
800		975	920	30	24	32
900		1075	1020	30	24	34
1000		1175	1121	30	28	36
1200	0.6	1400	1340	34	32	36
1400		1620	1560	34	36	40
1600		1820	1760	34	40	45
1800		2045	1970	41	44	45
2000		2265	2180	48	48	50

Plug-in electromagnetic part



The sensor consists of the following main parts or components:

- Detection head: including electrodes, excitation coil, iron core and leads, the shell is PVC or F4.
- •Insertion rod: connects the detection head and converter, made of 304 or 316 stainless steels.
- Installation parts: (60×3) 304 or 316 stainless steel pipe, welded to the user's pipe during installation.
- Valve or (pin joint): 2" stainless steel ball valve or (pin joint), used to remove or install the sensor without flow interruption.
- Sealing and locking mechanism: including transition pieces, compression nuts, and special sealing rubber rings.
- Junction box (integrated type directly connected to the converter): The excitation current and signal of the sensor and converter are connected correspondingly here.

Installation:

1. First, open a 60-62mm hole directly above the pipe measurement point. The edges around the hole must be smooth and clean, without burrs or gas cutting scars. Unscrew the installation piece from the sensor and reliably weld it to the above hole. For the hole, requirements: As shown in figure above, make the lower end of the installation piece flush with the inner surface of the pipe; ensure there is no leakage.

2.Record the L2 size, loosen the three locking screws of the sensor, and pull out the detection rod and detection head for later installation. (Note: The user must not open the connection between the detection head and the insertion rod!)

3. Wrap raw tape on the upper thread of the installation piece and tighten the ball valve together with the sealing and locking mechanism on it.

4.Slowly insert the detection rod from above, tighten the lock nut slightly, press down the insertion rod and measure that L2 is the same size as the original recorded L2, and the installation is complete. 5.Insertion depth adjustment: When the selector electrode is inserted into the average flow velocity, the average flow velocity point is approximately 30 meters away from the pipe wall under turbulent flow conditions in the pipeline.

H=0.25D (D is the inner diameter of the pipe, that is, the insertion depth is 1/4 of the pipe diameter). After adjustment, tighten the lock nut firmly and tighten the three locking screws respectively.

Tips and Notes: Since the pressure in the pipeline pushes the detection rod outward,


*For safety reasons, it is best to shut down the machine and install it under pressure-free conditions.


*If shutdown is not allowed, it is best to temporarily reduce the pipeline pressure to \leq 0.2MPa during installation.

-8-


Product Installation

Precautions






Grounding of flowmeter and pipeline




-10-




Non-metallic pipeline, sensor is equipped with grounding electrode.

Non-metallic pipeline, sensor without grounding electrode




Pipeline with cathodic protection

Electrical wiring Integrated converter series terminal block description



[+]	Flow current output				
COM:	Current output ground				
P+:	Bidirectional flow frequency (pulse)				
PT.	output				
COM:	Frequency (pulse) output ground				
AL:	Lower limit alarm output				
AH:	Lower limit alarm output				
COM:	Alarm output, GND				
FUSE:	Input power fuse				
T+:	Communication input(RS485-A)				
T-:	Communication input(RS485-B)				
G:	RS232 communication GND				
L1:	220V(24V) supply input				
Lz:	220V(24V) supply input				


Split converter series terminal block description




SIG 1	Signal 1				
SGND	Signal GND				
SIG 2	Signal 2	To connect sensor part			
DS1	Incentive shielding 1	of split flow meter			
DS2	Incentive shielding 2				
EXT +	Excitation current +				
EXT -	Excitation current -				
VDIN	24V power for 2-wire current				
VUIN	output	Analag augrant autaut			
IOUT	Analog current output	Analog current outpu			
ICOM	Analog current output GND				
POUT	Flow frequency (pulse) output	Flow frequency (pulse)			
РСОМ	Flow frequency (pulse) output GND	output output			
ALMH	Upper limit alarm output				
ALML	Lower limit alarm output	Two way alarm output			
ACOM	limit alarm output GND				
TRX+	Communication (RS485-A)	Communication			
TRX -	Communication (RS485-B)	Communication interface			
тсом	RS232 commmunication GND	плетасе			

Convertor Menus and Settings

Display interface and button functions



-12-



		Description				
Keys	The four keys are compound key, down key, up key and confirmation key from left to right. Select this function to enter the parameter setting screen, which has a 5-level					
	Parameters setting	Select this function to enter the parameter setting screen, which has a 5-level				
Functions	Parameters setting	password. Press the compound key + confirm key at the same time to enter.				
		Select this function to clear the total amount of the instrument. The password is				
Functions	Total amount cleared	10000. Press the compound key + confirm key at the same time to clear the				
L		instrument.				
	change record	Select this function to view the flow coefficient modification record				
	Level 1 Password	00521:User can only view instrument parameters				
	Level 2 Password	03210: User can change parameters with Password level ≤2				
Password	Level 3 Password	06108: User can change parameters with Password level ≤3				
	Level 4 Password	Please consult the manufactory				
	Level 5 Password	Please consult the manufactory				
		Up key: Cycle through the content displayed on the lower row of the screen				
	Key functions in automatic measurement	compound key + confirm key: enter parameter setting state				
	state	Confirm key: return to automatic measurement state				
	state	Brightness adjustment: increase the brightness through "compound key + up key",				
Basic key		and decrease brightness through "compound key + down key"				
funtions		Down key: Decrease the number at the cursor by 1				
IUIILIOIIS		Up key: Add 1 to the number at the cursor				
	Key functions in parameter setting state	compound key + down key: move the cursor left				
	key fullctions in parameter setting state	compound key + up key: move the cursor to the right				
		Confirm key: enter/exit the submenu; in any state, press and hold for a few seconds				
		to return to the main measurement status page				

Parameter setting method: To set or modify instrument parameters, the instrument must enter the parameter setting state from the measurement state. In the measurement state, press the "compound key + confirm key", the instrument will enter the function selection screen "Parameter Settings", then press the confirmation key to enter the password input state "00000", enter the password and press the "compound key + confirm key" enter the parameter setting screen.

Parameter setting menu list

arameter number	Parameter Display	Display parameter content		Parameter range	Passwor level
1	Language	Language	Choice	Chinese, English	2
2	CommAddres	Instrument communication address	Set value	0 ~ 254	2
3	Baud Rate	Instrument communication speed	Choice	300 ~ 38400	2
4	Snsr Size	Measure pipe diameter	Choice	3 ~ 3000	2
5	Flow Unit	flow unit	Choice	L/h,L/m,L/s,m3/h,m3/m,m3/s, T/h,T/m,T/s	2
6	Flow Range	Instrument range setting	Set value	0 ~ 99999	2
7	Flow Rspns	Measure damping time	Choice	1 ~ 50	2
8	Flow Direct	Traffic direction selection	Choice	Forward / reverse	2
9	Flow Zero	Flow zero point correction	Set value	0~±9999	2
10	Flow Cutoff	small signal cutoff point	Set value	0~599.99%	2
11	Cutoff Ena	Allow cut display	Choice	Allow/Forbidden	2
12	Total Unit	Flow accumulation unit	Choice	0.001m3~1m3、0.001L~1L、0.001T~1T	2
13	Density	fluid density	Set value	0-3.999T/m³	2
14	SegmaN Ena	Reverse output allowed	Choice	Allow/Forbidden	2
15	Analog Type	Current output type	Choice	4 ~ 20mA/4mA	2
16	Pulse Type	Pulse output mode	Choice	frequency/pulse	2
17	Pulse Fact	Pulse unit equivalent	Choice	0.001m ³ ~1m ³ 、0.001L~1L、0.001T~1T	2
18	Freque Max	Frequency output range	Choice	1 ~ 5999 Hz	2
19	Mtsnsr Ena	empty tube alarm allowed	Choice	Allow/Forbidden	2
20	MtsnsrTrip	Empty pipe alarm threshold	Set value	0~59999	2
21	Alm Hi Ena	Upper limit alarm allowed	Choice	Allow/Forbidden	2
22	Alm Hi Val	Upper limit alarm value	Set value	000.0~599.99 %	2
23	Alm Lo Ena	Lower limit alarm allowed	Choice	Allow/Forbidden	2
24	Alm Lo Val	Lower limit alarm value	Set value	000.0~599.99 %	2
25	Sys Alm Ena	Excitation alarm allowed	Choice	Allow/Forbidden	2
26	ClrSum Key	Total flow reset password	Set value	0-9999	3
27	Snsr Code1	Sensor code 1	user settings	Year and month of manufacture(0-99999)	4
28	Snsr Code2	Sensor code 2	user settings	Product number(0-99999)	4
29	Field Type	Excitation mode selection	Choice	Mode 1, 2, 3	4
30	Sensor Fact	Sensor factor value	Set value	0.0000 ~ 5.9999	4
31	Line Crc Ena	Traffic correction allowed	Choice	Allow/Forbidden	2
32	Lineary CRC1	Flow correction point 1	user settings	Set by flow rate	4
33	LinearyFact1	Flow correction number 1	user settings	0.0000 ~ 1.9999	4
34	Lineary CRC2	Flow correction point 2	user settings	Set by flow rate	4
35	LinearyFact2	Flow correction number 2	user settings	0.0000 ~ 1.9999	4
36	Lineary CRC3	Flow correction point 3	user settings	Set by flow rate	4
37	LinearyFact3	Flow correction number 3	user settings	0.0000 ~ 1.9999	4
38	Lineary CRC4	Flow correction point 4	user settings	Set by flow rate	4
39	LinearyFact4	Flow correction number 4	user settings	0.0000 ~ 1.9999	4
40	FwdTotalLo	Forward total low	Can be modified	00000 ~ 99999	5
41	FwdTotalHi	Forward total high level	Can be modified	0000 ~ 9999	5
42	RevTotalLo	Reverse total low	Can be modified	00000 ~ 99999	5
43	RevTotalHi	Reverse total high	Can be modified	0000 ~ 9999	5
44	PlsntLmtEna	Spike suppression allows	Choice	Allow/Forbidden	3
45	PlsntLmtVal	spike suppression coefficient	Choice	0.010 ~ 0.800m/s	3
46	Plsnt Delay	spike suppression time	Choice	400 ~ 2500ms	3
47	PassWord 1	Password Level 1	User can change	00000 ~ 99999	5
48	PassWord 2	Password Level 2	User can change	00000 ~ 99999	5
49	PassWord 3	Password Level 3	User can change	00000 ~ 99999	5
50	PassWord 4	Password Level 4	User can change	00000 ~ 99999	5
51	AnalogZero	Current zero point correction	Set value	0.0000 ~1.9999	5
52	Anlg Range	Current span point correction	Set value	0.0000 ~1.9999	5
53	Meter Fact	Factory calibration coefficient	Set value	0.0000 ~ 3.9999	5
53	MeterCode1				6
		Convertor code 1	Factory settings	Year and month of manufacture(0-99999)	
55	MeterCode2	Convertor code 2	Factory settings	Product number(0-99999)	6
56	Check Mode	Communication verification mode	Factory settings	No Parity Stop1、Odd Parity Stop1、Even Parity Stop1、No Parity Stop2、Odd Parity Stop2、Even Parity Stop2	2
57	MtsnsrZero	Empty pipe zero point correction	Factory settings	00000~19999	2
58	MtsnsrRange	Empty pipe range correction	Factory settings	00000~59999	2

Note: Instrument parameters determine the operating status, calculation method, output mode and status of the instrument. Correct selection and setting of instrument parameters can make the instrument runs in the best condition and obtains high measurement display accuracy and measurement output accuracy.

-14-

HFM100 Electromagnetic Flowmeter

HFM100 Electromagnetic Flowmeter

Detailed description of parameters

Parameter number	Parameter content	Parameter detail description						
1	Language	Converter is available in Chinese and English, and users can choose to operate it by themselves.						
2	Instrument communication address	Refers to the communication address of this watch when communicating with multiple machines. The optional range s: addresses 01 to 254. Address 0 is reserved.						
3	Instrument communication speed	Instrument communication baud rate selection range: 300, 1200, 2400, 4800, 9600, 38400.						
4	Measure pipe diameter	The sensor diameter range of the electromagnetic flowmeter converter is 3~3000 mm.						
5	flow unit	Select the flow display unit in the parameters. The instrument flow display units are: L/s, L/m, L/h, m³/s, m³/m, m³/h, T/s, T/m, T/h User A suitable flow display unit can be selected according to process requirements and usage habits.						
6	Instrument range setting	Instrument range setting refers to determining the upper limit flow value, and the lower limit flow value of the instrument is automatically set to "0". Therefore, the meter range setting determines the meter range, and also determines the meter percentage display, meter frequency output, meter voltage The corresponding relationship between stream output and traffic: Meter percentage display value = (flow value measurement value / meter range) * 100%; Instrument frequency output value = (flow value measurement value / instrument range range) * frequency full range value; Instrument current output value = (flow value measurement value / instrument range) * current full range value + base point; The instrument pulse output value is not affected by the instrument range setting;						
7	Measure damping time	A long measurement filter time can improve the stability of the instrument flow display and the stability of the output signal and is suitable for total cumulative pulsating flow measurement. The short measurement filter time shows fast measurement response speed, which is suitable for production process control. The measurement filter time is set by selection.						
8	Traffic direction	If the user thinks that the fluid direction during debugging is inconsistent with the design, the user does not need to						
	selection	change the excitation line or signal line connection but can use the flow direction setting parameters to change it.						
9	Flow zero-point correction	When performing zero-point correction, ensure that the sensor tube is filled with fluid and the fluid is at rest. The flow zero point is expressed by flow velocity, and the unit is mm/s. The converter flow zero point correction is displayed as follows: FS = 0 0 0 0 0 0						
10	small signal cutoff point	The small signal cutoff point setting is expressed as a percentage flow rate of the range. When cutting off small signals, the user can choose to cut off the display and signal output of flow rate, flow rate and percentage at the same time; or they can choose to cut off only the current output signal and frequency (pulse) output signal while maintaining the display of flow rate, flow rate and percentage.						
12	Flow accumulation unit	The converter display is a 9-digit counter, and the maximum allowed count value is 999999999. The cumulative units used are L, m³,T (liter, cubic meter, ton). The flow accumulation equivalent is: 0.001L, 0.010L, 0.100L, 1.000L 0.001m³, 0.001m³, 1.000m³, 1.000m³ 0.001T, 0.010T, 0.100T, 1.000T;						

12										
13	fluid density	This menu works when the mass unit T/s, T/m, T/h is selected in "Fluid Unit".								
14	Reverse output When the reverse output permission parameter is set to the "allow" state, as long as the fluid flows, the convalued output pulses and current according to the flow value.									
	allowed									
		When the reverse output pe				reverse direction, the				
		converter output pulse is "0" and the current output is the signal "0" (4mA or 0mA).								
15	Current output type	Users can select current output in the current output type.								
16	Pulse output mode	There are two pulse output modes to choose from: frequency output and pulse output: Frequency output mode: The frequency output is a continuous square wave, and the frequency value corresponds to								
		the flow rate percentage.	ie frequency output	is a continuous square wav	e, and the freque	ncy value corresponds to				
		Frequency output value = (flow value measure	ment value / instrument rar	nge) * frequency f	full range value;				
		Pulse output mode: The pul	lse output is a recta	ngular wave pulse train. Ea	ch pulse represen	ts a flow equivalent				
		flowing through the pipelin								
		Select the "Pulse Equivalent and is generally connected			le is mostly used	for total accumulation				
		Frequency output and pulse			Therefore, an ext	ternal DC power supply				
		and load should be connect		,						
17	Pulse unit equivalent	The pulse unit equivalent re	efers to the flow value	ue represented by one puls	e. The instrument	t pulse equivalent				
		selection range is as below								
		Under the same flow rate, it cumulative flow error will be	Under the same flow rate, if the pulse equivalent is small, the frequency of output pulses will be high, and the							
				Dulas and balant	Flores	ı				
		Pulse equivalent	Flow	Pulse equivalent 7	Flow 0.1m2/cm					
		1 2	0.001L/cp 0.01L/cp	8	0.1m3/cp 1.0m3/cp					
		3	0.1L/cp	9	0.001T/cp					
		4	1.0L/cp	10	0.0017/cp					
		5	0.001m3/cp	11	0.1T/cp					
		6	0.01m3/cp	12	1.0T/cp					
		The frequency output range of the instrument corresponds to the upper limit of flow measurement, which is 100% of the percentage flow. The frequency output upper limit can be set arbitrarily within the range of 1–5000Hz.								
18	Frequency output range									
19			equency output upp function and does ument can detect ar the empty pipe stati	per limit can be set arbitrari not require additional elect n empty pipe status when t us is detected, the analog o	ly within the rang trodes. If the user he fluid in the pip utput and digital	e of 1~5000Hz. chooses to allow the se is lower than the				
	range empty tube alarm	the percentage flow. The from It has empty pipe detection empty pipe alarm, the instru- measuring electrode. After the	equency output upp function and does ument can detect ar the empty pipe state the flow rate of the i	per limit can be set arbitrari not require additional elect n empty pipe status when t us is detected, the analog o nstrument is displayed as z	ly within the rang trodes. If the user he fluid in the pip utput and digital ero.	e of 1~5000Hz. chooses to allow the se is lower than the output of the instrument				
19	range empty tube alarm allowed	the percentage flow. The fir It has empty pipe detection empty pipe alarm, the instrr measuring electrode. After it are set to signal zero, and ti When the pipe is full of flui make it more convenient fo	equency output upp function and does ument can detect ar the empty pipe state he flow rate of the i d (either with or with or users. The upper l	per limit can be set arbitrari not require additional elect n empty pipe status when t us is detected, the analog o onstrument is displayed as z hout flow rate), the empty ine of the empty pipe alarn	ly within the rang trodes. If the user he fluid in the pip utput and digital ero. pipe alarm setting n threshold param	e of 1~5000Hz. chooses to allow the be is lower than the output of the instrument g has been modified to neter displays the				
19	range empty tube alarm allowed Empty pipe alarm	the percentage flow. The fir- lt has empty pipe detection empty pipe alem, the instru- measuring electrode. After tare set to signal zero, and ti When the pipe is full of flui- make it more convenient for measured conductivity, and	equency output upp function and does ument can detect at the empty pipe state he flow rate of the i d (either with or with or users. The upper I I the lower line sets	per limit can be set arbitrari not require additional elect n empty pipe status when t us is detected, the analog o nstrument is displayed as z hout flow rate), the empty ine of the empty pipe alarm the empty pipe alarm thres	ly within the rang trodes. If the user he fluid in the pip utput and digital ero. pipe alarm setting h threshold param shold. When setting	e of 1~5000Hz. chooses to allow the be is lower than the output of the instrument g has been modified to neter displays the ng the empty pipe alarm				
19	range empty tube alarm allowed Empty pipe alarm	the percentage flow. The fir It has empty pipe detection empty pipe alarm, the instrr measuring electrode. After it are set to signal zero, and ti When the pipe is full of flui make it more convenient fo	equency output upp function and does ument can detect at the empty pipe state he flow rate of the i d (either with or with or users. The upper I I the lower line sets	per limit can be set arbitrari not require additional elect n empty pipe status when t us is detected, the analog o nstrument is displayed as z hout flow rate), the empty ine of the empty pipe alarm the empty pipe alarm thres	ly within the rang trodes. If the user he fluid in the pip utput and digital ero. pipe alarm setting h threshold param shold. When setting	e of 1~5000Hz. chooses to allow the be is lower than the output of the instrument g has been modified to neter displays the ng the empty pipe alarm				
19	range empty tube alarm allowed Empty pipe alarm	the percentage flow. The fir It has empty pipe detection empty pipe alarm, the instra measuring electrode. After are set to signal zero, and the When the pipe is full of fluir make it more convenient for measured conductivity, and threshold, it can be set acce.	equency output up; I function and does ument can detect at the empty pipe state the flow rate of the i d (either with or wit or users. The upper I the lower line sets ording to the measu	per limit can be set arbitrari not require additional elect n empty pipe status when t us is detected, the analog o nstrument is displayed as z hout flow rate), the empty ine of the empty pipe alarm the empty pipe alarm thres	ly within the rang trodes. If the user he fluid in the pip utput and digital ero. pipe alarm setting h threshold param shold. When setting	e of 1~5000Hz. chooses to allow the be is lower than the output of the instrument g has been modified to neter displays the ng the empty pipe alarm				
19	empty tube alarm allowed Empty pipe alarm threshold Upper limit alarm	the percentage flow. The fir It has empty pipe detection empty pipe alarm, the instri- measuring electrode. After it are set to signal zero, and it When the pipe is full of fluir make it more convenient for measured conductivity, and threshold, it can be set acco- conductivity. User chooses to allow or di	equency output up; function and does ument can detect at the empty pipe statu he flow rate of the i d (either with or wit or users. The upper I I the lower line sets ording to the measu sallow	per limit can be set arbitrari not require additional elect ne empty pipe status when t us is detected, the analog o nstrument is displayed as z hout flow rate), the empty ine of the empty pipe alarm the empty pipe alarm threed conductivity, and it can	ly within the rang trodes. If the user he fluid in the pip utput and digital ero. pipe alarm setting in threshold param shold. When setting be set to 3 to 5 to 10 to 10 to	ee of 1~5000Hz. chooses to allow the tee is lower than the output of the instrument g has been modified to to teter displays the times the measured				
20	empty tube alarm allowed Empty pipe alarm threshold Upper limit alarm allowed	the percentage flow. The fir It has empty pipe detection empty pipe alarm, the instr measuring electrode. After are set to signal zero, and the When the pipe is full of fluir make it more convenient for measured conductivity, and threshold, it can be set acco conductivity.	function and does unent can detent at the empty pipe state the flow rate of the i d (either with or with the lower line sets ording to the measurable is calculated as a p use between 0% and	per limit can be set arbitrari not require additional elect in empty pipe status when t us is detected, the analog o nstrument is displayed as z hout flow rate), the empty pine alarm the empty pipe alarm the serviced conductivity, and it can be considered to the conductivity, and it can be considered to the conductivity.	ly within the rang crodes. If the user he fluid in the pip utput and digital ero. pipe alarm setting it threshold param thold. When settir is be set to 3 to 5 to s parameter adops	e of 1~5000Hz. chooses to allow the e is lower than the output of the instrument g has been modified to neter displays the ng the empty pipe alarm times the measured ots the numerical setting				
20	range empty tube alarm allowed Empty pipe alarm threshold Upper limit alarm allowed Upper limit alarm value Lower limit alarm	the percentage flow. The fir It has empty pipe detection empty pipe alarm, the instru- measuring electrode. After i- are set to signal zero, and the When the pipe is full of fluir make it more convenient for measured conductivity, and threshold, it can be set acce conductivity. User chooses to allow or di- The upper limit alarm value method. The user sets a vali-	function and does ument can detect an the empty pipe stath the flow rate of the i d (either with or wit r users. The upper I the lower line sets ording to the measu sallow is calculated as a p will output an alarm	per limit can be set arbitrari not require additional elect in empty pipe status when t us is detected, the analog o nstrument is displayed as z hout flow rate), the empty pine alarm the empty pipe alarm the serviced conductivity, and it can be considered to the conductivity, and it can be considered to the conductivity.	ly within the rang crodes. If the user he fluid in the pip utput and digital ero. pipe alarm setting it threshold param thold. When settir is be set to 3 to 5 to s parameter adops	e of 1~5000Hz. chooses to allow the e is lower than the output of the instrument g has been modified to neter displays the ng the empty pipe alarm times the measured ots the numerical setting				
20 21 22	empty tube alarm allowed Empty pipe alarm threshold Upper limit alarm allowed Upper limit alarm value	the percentage flow. The fir It has empty pipe detection empty pipe alarm, the instri- measuring electrode. After it are set to signal zero, and it When the pipe is full of fluir make it more convenient for measured conductivity, and threshold, it can be set acce conductivity. User chooses to allow or dir- The upper limit alarm value method. The user sets a vali instrument, the instrument	function and does ument can detect an the empty pipe stath the flow rate of the i d (either with or wit r users. The upper I the lower line sets ording to the measu sallow is calculated as a p will output an alarm	per limit can be set arbitrari not require additional elect in empty pipe status when t us is detected, the analog o nstrument is displayed as z hout flow rate), the empty pine alarm the empty pipe alarm the serviced conductivity, and it can be considered to the conductivity, and it can be considered to the conductivity.	ly within the rang crodes. If the user he fluid in the pip utput and digital ero. pipe alarm setting it threshold param thold. When settir is be set to 3 to 5 to s parameter adops	e of 1~5000Hz. chooses to allow the e is lower than the output of the instrument g has been modified to neter displays the ng the empty pipe alarm times the measured ots the numerical setting				
20 21 22	range empty tube alarm allowed Empty pipe alarm threshold Upper limit alarm allowed Upper limit alarm value Lower limit alarm	the percentage flow. The fir It has empty pipe detection empty pipe alarm, the instri- measuring electrode. After it are set to signal zero, and it When the pipe is full of fluir make it more convenient for measured conductivity, and threshold, it can be set acce conductivity. User chooses to allow or dir- The upper limit alarm value method. The user sets a vali instrument, the instrument	equency output up; function and does ument can detect at the empty pipe state he flow rate of the i d (either with or wit r users. The upper the lower line sets prding to the measu sallow is calculated as a p ue between 0% and will output an alarm sallow	per limit can be set arbitrari not require additional elect on empty pipe status when tus is detected, the analog o nstrument is displayed as z hout flow rate), the empty pine of the empty pipe alarm the empty pipe alarm thres tred conductivity, and it can exceed the empty pipe alarm thres tred conductivity, and it can exceed the empty pipe alarm thres tred conductivity, and it can exceed the empty pipe alarm thres tred conductivity, and it can exceed the empty pipe alarm thres tred conductivity, and it can be exceeded the empty pipe alarm thres tred the empty pipe alarm thres tred the empty pipe alarm thres tred the empty pipe alarm threshold threshol	ly within the rang grodes, If the user he fluid in the pip utput and digital ero. pipe alarm setting threshold param shold. When settin to be set to 3 to 5 to s parameter adoptions are met dur	e of 1~5000Hz. chooses to allow the be is lower than the output of the instrument g has been modified to neter displays the ng the empty pipe alarm times the measured ots the numerical setting ing operation of the				
20 21 22 23	empty tube alarm allowed Empty pipe alarm threshold Upper limit alarm allowed Lower limit alarm allowed Excitation alarm	the percentage flow. The fir It has empty pipe detection empty pipe alarm, the instr measuring electrode. After are set to signal zero, and the When the pipe is full of fluir make it more convenient for measured conductivity, and threshold, it can be set acco conductivity. User chooses to allow or direction. The upper limit alarm value method. The user sets a valuinstrument, the instrument User chooses to allow or directions.	function and does ument can detect at the empty pipe state the flow rate of the id (d (either with or with visual rate of the id the lower line sets ording to the measure sallow is calculated as a p use between 0% and will output an alarm sallow excitation alarm fun	per limit can be set arbitrari not require additional elect no empty pipe status when t us is detected, the analog o nstrument is displayed as z hout flow rate), the empty pine of the empty pipe alarm the street conductivity, and it car ercentage of the range. This is gignal.	ly within the rang crodes. If the user he fluid in the pip utput and digital ero. pipe alarm setting threshold param shold. When setting be set to 3 to 5 to s parameter adoptions are met dur cell the excitation.	e of 1~5000Hz. chooses to allow the es is lower than the output of the instrument g has been modified to the to the to the test of the the test of the the test of the test				
20 21 22 23 25	empty tube alarm allowed Empty pipe alarm threshold Upper limit alarm allowed Upper limit alarm value Lower limit alarm allowed Excitation alarm allowed Total flow reset	the percentage flow. The fir It has empty pipe detection empty pipe alarm, the instr- measuring electrode. After are set to signal zero, and it When the pipe is full of fluir make it more convenient for measured conductivity, and threshold, it can be set acco conductivity. User chooses to allow or dir The upper limit alarm value method. The user sets a vali instrument, the instrument User chooses to allow or dir Select Allow to enable the e Users who use passwords o	equency output up; function and does ument can detect at the empty pipe state he flow rate of the i r users. The upper i the lower line sets rding to the measu sallow is calculated as a p ue between 0% and will output an alarm sallow file the sets for the control of the sets for the sets fo	ner limit can be set arbitrari not require additional elect on empty pipe status when t us is detected, the analog o nstrument is displayed as z hout flow rate), the empty pipe alarm the empty pipe alarm three red conductivity, and it can ercentage of the range. This pipe, so the same conductivity, and it can exceed the pipe. The same conductivity is signal.	ly within the rang grodes. If the use he fluid in the pip to the fluid in the pip utput and digital ero. pippe alarm setting threshold param shold. When setting the set to 3 to 5 to s parameter adoptions are met dur the set the set and then set the parameter and the parameter	e of 1~5000Hz. chooses to allow the be is lower than the output of the instrument o				

-16-

29		
	Excitation mode selection	The converter provides three excitation frequency options: 1/16 power frequency (mode 1), 1/20 power frequency (mode 2), 1/25 power frequency (mode 2)
	selection	
		3). The inductance of the small-diameter sensor excitation system is small, so 1/16 power frequency should be
		selected. The excitation system of large-diameter sensors has large inductance, and users can only choose 1/20
		power frequency or 1/25 power frequency. During use, select excitation mode 1 first. If the zero point of the flow rate
		of the instrument is too high, select mode 2 or mode 3 in sequence. Note: In which excitation mode it is calibrated, it
		must be operated in which excitation mode.
30	Sensor Factor value	Sensor factor: that is, the calibration coefficient of the electromagnetic flowmeter. This coefficient is obtained from
		the actual standard and stamped on the sensor nameplate. The user must place this coefficient in the converter
		parameter table.
40	Forward total low	The total high and low bit settings can change the values of forward cumulative total and reverse cumulative total
		and are mainly used for instrument maintenance and instrument replacement.
41	Forward total high	
	level	Users can use the level 5 password to enter and modify the forward accumulation amount (Σ+). Generally, the
		accumulated amount cannot exceed the maximum value calculated by the counter (999999999).
42	Reverse total low	Users can use the level 5 password to enter and modify the reverse accumulation amount (Σ-). Generally, the
43	Reverse total high	accumulation amount cannot exceed the maximum value calculated by the counter (999999999).
45	neverse total liigh	decimation amount earner exceed the maximum value calculated by the counter (55555555).
44	Spike suppression	For flow measurement of pulp, mud and other slurries, solid particles in the fluid rub or impact the measurement
	allows	electrode, which will form "peak interference". To overcome such interference, the converter adopts a change rate
		suppression algorithm. The converter is designed with three parameters to select the change rate suppression
		characteristics.
		Set this parameter to "Allow" to start the change rate suppression algorithm. Set this parameter to "disabled" to turn
		off the change rate suppression algorithm.
1		
45	spike suppression	This coefficient selects the rate of change to suppress sharp interference. Calculated according to the percentage of
	coefficient	flow velocity, it is divided into 0.010m/s, 0.020m/s, 0030m/s, 0.050m/s, 0.080m/s, 0.100m/s, Among the levels of
		0.200m/s, 0.300m/s, 0.500m/s, and 0.800m/s+, the smaller the level percentage, the higher the sensitivity of peak
		interference suppression.
		Note: in application, the selection should be made experimentally based on the actual situation. Higher sensitivity
		is not always the best.
46	spike suppression	is not always the best. This parameter selects the time width to suppress peak interference, in milliseconds. Flow changes lasting less than
46	spike suppression time	
46		This parameter selects the time width to suppress peak interference, in milliseconds. Flow changes lasting less than
46		This parameter selects the time width to suppress peak interference, in milliseconds. Flow changes lasting less than the selected time are considered spikes by the converter. Flow changes lasting longer than the selected time are
46		This parameter selects the time width to suppress peak interference, in milliseconds. Flow changes lasting less than the selected time are considered spikes by the converter. Flow changes lasting longer than the selected time are considered normal flow changes by the converter. This parameter should also be selected experimentally based on
47	time Password Level 1	This parameter selects the time width to suppress peak interference, in milliseconds. Flow changes lasting less than the selected time are considered spikes by the converter. Flow changes lasting longer than the selected time are considered normal flow changes by the converter. This parameter should also be selected experimentally based on
	time	This parameter selects the time width to suppress peak interference, in milliseconds. Flow changes lasting less than the selected time are considered spikes by the converter. Flow changes lasting longer than the selected time are considered normal flow changes by the converter. This parameter should also be selected experimentally based on
47 48	Password Level 1 Password Level 2	This parameter selects the time width to suppress peak interference, in milliseconds. Flow changes lasting less than the selected time are considered spikes by the converter. Flow changes lasting longer than the selected time are considered normal flow changes by the converter. This parameter should also be selected experimentally based on
47	time Password Level 1	This parameter selects the time width to suppress peak interference, in milliseconds. Flow changes lasting less than the selected time are considered spikes by the converter. Flow changes lasting longer than the selected time are considered normal flow changes by the converter. This parameter should also be selected experimentally based on the actual situation.
47	Password Level 1 Password Level 2	This parameter selects the time width to suppress peak interference, in milliseconds. Flow changes lasting less than the selected time are considered spikes by the converter. Flow changes lasting longer than the selected time are considered normal flow changes by the converter. This parameter should also be selected experimentally based on the actual situation.
47 48 49	Password Level 1 Password Level 2 Password Level 3	This parameter selects the time width to suppress peak interference, in milliseconds. Flow changes lasting less than the selected time are considered spikes by the converter. Flow changes lasting longer than the selected time are considered normal flow changes by the converter. This parameter should also be selected experimentally based on the actual situation.
47 48 49 50	Password Level 1 Password Level 2 Password Level 3 Password Level 4	This parameter selects the time width to suppress peak interference, in milliseconds. Flow changes lasting less than the selected time are considered spikes by the converter. Flow changes lasting longer than the selected time are considered normal flow changes by the converter. This parameter should also be selected experimentally based on the actual situation. Users use level 5 password to enter and can modify these passwords
47 48 49 50 51	Password Level 1 Password Level 2 Password Level 3 Password Level 4 Current zero-point correction	This parameter selects the time width to suppress peak interference, in milliseconds. Flow changes lasting less than the selected time are considered spikes by the converter. Flow changes lasting longer than the selected time are considered normal flow changes by the converter. This parameter should also be selected experimentally based on the actual situation. Users use level 5 password to enter and can modify these passwords The current output zero point of the converter is adjusted at the factory so that the current output is accurately 0mA or 4mA.
47 48 49 50	Password Level 1 Password Level 2 Password Level 3 Password Level 4 Current zero-point correction Current full point	This parameter selects the time width to suppress peak interference, in milliseconds. Flow changes lasting less than the selected time are considered spikes by the converter. Flow changes lasting longer than the selected time are considered normal flow changes by the converter. This parameter should also be selected experimentally based on the actual situation. Users use level 5 password to enter and can modify these passwords The current output zero point of the converter is adjusted at the factory so that the current output is accurately 0mA
47 48 49 50	Password Level 1 Password Level 2 Password Level 3 Password Level 4 Current zero-point correction	This parameter selects the time width to suppress peak interference, in milliseconds. Flow changes lasting less than the selected time are considered spikes by the converter. Flow changes lasting longer than the selected time are considered normal flow changes by the converter. This parameter should also be selected experimentally based on the actual situation. Users use level 5 password to enter and can modify these passwords The current output zero point of the converter is adjusted at the factory so that the current output is accurately 0mA or 4mA.
47 48 49 50	Password Level 1 Password Level 2 Password Level 3 Password Level 4 Current zero-point correction Current full point correction Factory calibration	This parameter selects the time width to suppress peak interference, in milliseconds. Flow changes lasting less than the selected time are considered spikes by the converter. Flow changes lasting longer than the selected time are considered normal flow changes by the converter. This parameter should also be selected experimentally based on the actual situation. Users use level 5 password to enter and can modify these passwords The current output zero point of the converter is adjusted at the factory so that the current output is accurately 0mA or 4mA. The current output full point adjusted at the factory so that the current output is accurately 10mA or 20mA. This coefficient is a dedicated coefficient for the converter manufacturer. The converter manufacturer uses this
47 48 49 50 51	Password Level 1 Password Level 2 Password Level 3 Password Level 4 Current zero-point correction Current full point correction	This parameter selects the time width to suppress peak interference, in milliseconds. Flow changes lasting less than the selected time are considered spikes by the converter. Flow changes lasting longer than the selected time are considered normal flow changes by the converter. This parameter should also be selected experimentally based on the actual situation. Users use level 5 password to enter and can modify these passwords The current output zero point of the converter is adjusted at the factory so that the current output is accurately 0mA or 4mA. The current output full point adjusted at the factory so that the current output is accurately 10mA or 20mA. This coefficient is a dedicated coefficient for the converter manufacturer. The converter manufacturer uses this coefficient to normalize the electromagnetic converter measurement circuit system to ensure that the
47 48 49 50 51	Password Level 1 Password Level 2 Password Level 3 Password Level 4 Current zero-point correction Current full point correction Factory calibration	This parameter selects the time width to suppress peak interference, in milliseconds. Flow changes lasting less than the selected time are considered spikes by the converter. Flow changes lasting longer than the selected time are considered normal flow changes by the converter. This parameter should also be selected experimentally based on the actual situation. Users use level 5 password to enter and can modify these passwords The current output zero point of the converter is adjusted at the factory so that the current output is accurately 0mA or 4mA. The current output full point adjusted at the factory so that the current output is accurately 10mA or 20mA. This coefficient is a dedicated coefficient for the converter manufacturer. The converter manufacturer uses this
47 48 49 50 51 52 53	Password Level 1 Password Level 2 Password Level 3 Password Level 4 Current zero-point correction Current full point correction Factory calibration coefficient	This parameter selects the time width to suppress peak interference, in milliseconds. Flow changes lasting less than the selected time are considered spikes by the converter. Flow changes lasting longer than the selected time are considered normal flow changes by the converter. This parameter should also be selected experimentally based on the actual situation. Users use level 5 password to enter and can modify these passwords The current output zero point of the converter is adjusted at the factory so that the current output is accurately 0mA or 4mA. The current output full point adjusted at the factory so that the current output is accurately 10mA or 20mA. This coefficient is a dedicated coefficient for the converter manufacturer. The converter manufacturer uses this coefficient to normalize the electromagnetic converter measurement circuit system to ensure that the
47 48 49 50 51	Password Level 1 Password Level 2 Password Level 3 Password Level 4 Current zero-point correction Current full point correction Factory calibration	This parameter selects the time width to suppress peak interference, in milliseconds. Flow changes lasting less than the selected time are considered spikes by the converter. Flow changes lasting longer than the selected time are considered normal flow changes by the converter. This parameter should also be selected experimentally based on the actual situation. Users use level 5 password to enter and can modify these passwords The current output zero point of the converter is adjusted at the factory so that the current output is accurately 0mA or 4mA. The current output full point adjusted at the factory so that the current output is accurately 10mA or 20mA. This coefficient is a dedicated coefficient for the converter manufacturer. The converter manufacturer uses this coefficient to normalize the electromagnetic converter measurement circuit system to ensure that the

56	Communication verification mode	The converter comes standard with standard MODBUS communication 8-bit no parity mode (No Parity), and users can choose odd parity mode (Odd Parity) and even parity mode (Even Parity) as needed.						
57	Empty pipe zero-point correction	When the on-site full pipe value is large, the user can perform empty pipe zero-point correction. When performing zero-point correction on an empty pipe, ensure that the sensor is filled with fluid. The empty pipe zero-point correction is displayed as follows: $FS = \begin{array}{ccccccccccccccccccccccccccccccccccc$						
		The upper line displays: FS represents the empty pipe zero-point measurement value of the instrument. The lower line displays: Empty pipe zero-point correction value. First, according to the measured conductivity ratio MT value, adjust the correction value so that FS=5-10 (note: if the downward correction value is increased, the FS value will decrease)						
58	Empty pipe range correction	When the empty pipe conductance measured by the instrument is smaller than the MT value, the user can correct the empty pipe range. When performing zero-point correction on an empty pipe, ensure that there is no fluid in the sensor pipe. The empty tube range correction is displayed as follows: $FS = 0 1 0 0 0$ The upper line displays: FS represents the measured value of the empty pipe range of the instrument. The lower line displays: Empty pipe range correction value. Increasing the downward correction value increases the FS value. Decreasing the downward correction value reduces the FS value. Users can adjust FS to an appropriate value according to actual needs (it is recommended to adjust to FS=1000 or so), then the measured conductivity ratio when the pipe is empty is basically the actual corrected FS value.						

-18-

Alarm information

The printed circuit board of the electromagnetic flow converter uses surface welding technology and is not repairable to the user. Therefore, the user CANNOT open the converter housing. The 4-key intelligent converter has self-diagnosis function. Except for power supply and hardware circuit failures, alarm information can be correctly given for failures in general applications. This alarm information is prompted with " on the left side of the display. In the measuring state, the instrument automatically displays the fault.

The content of the fault is as follows:

FQH---- Flow upper limit alarm; FQL---- Flow lower limit alarm.

FGP---- fluid empty pipe alarm; SYS---- system excitation alarm.

Troubleshooting


No.	Problem description	How to handle
1	The instrument has no display	*Check whether the power is on;
		*Check whether the power fuse is intact;
		*Check whether the power supply voltage meets the requirements;
2	Excitation alarm	*Whether the excitation wiring EX1 and EX2 are open circuit;
		*Whether the total resistance of the sensor excitation coil is less than 150 Ω ;
		*If both are normal, the converter is faulty.
3	Air traffic control alarm	*Check whether the fluid fills the sensor measuring tube;
		*Use wires to short-circuit the converter signal input terminals SIG1, SIG2 and SGND. If the
		"empty pipe" prompt is cleared currently, it means the converter is normal. It may be that the
		conductivity of the measured fluid is low or the empty pipe threshold is set incorrectly;
		*Check whether the signal connection is correct;
		*Check whether the sensor electrode is normal:
		Make the flow rate zero, and the observation shows that the conductance ratio should be less
		than 100%;
		When there is flow, the resistance of the measured terminals SIG1 and SIG2 to SGND should be
		less than $50 k\Omega$ (for the medium is water, it is best to use a pointer multimeter to measure, and
		you can see the charging and discharging phenomenon during the measurement process).
		Use a multimeter to measure the DC voltage between DS1 and DS2 and it should be less than 1V.
		Otherwise, it means that the sensor electrode is contaminated and should be cleaned.
4	Measured flow rate incorrect	*Whether the fluid fills the sensor measuring tube;
		*Whether the signal line connection is normal;
		*Check whether the sensor factor and sensor zero point are set according to the sensor label or
		factory calibration sheet;

Lightning protection function description

When installing, the user MUST connect the grounding point of the converter terminal to the shell and then reliably ground it, Because the lightning protection gas arrester guides lightning strikes into the earth through the casing.

If the shell is not reliably grounded, once someone operates the converter during a lightning strike, personal accidents may occur.

See the connection diagram for details:



Ordering Guide

Model No.	Туре										
HFM100	Electromagnetic Flowmeter										
	Code	Mounting method									
	S	Flange type									
	С	Plug-in type									
		Code	Convertor type								
		1	Integrated								
		D	Split								
			Code	Nominal diameter							
			6	DN6							
			10	DN10							
			3000	DN3000							
				Code	Liner material						
				CR	Polychloroprene Rubber						
				PU	polyurethane rubber						
				FP	Silicone fluorine rubber						
				FE	PTFE						
				F46	Polyperfluoroethylene						
				PF	PFA						
					Code S6	Electrode material 316L					
					HC HC	Hastelloy C					
					TI	titanium					
					TA	Tantalum					
					WC	Tungsten Carbide					
					PT	Platinum-Iridium Alloy Code	D. I				
						TG	Body material carbon steel				
						S4	304				
						\$6	316L				
							Code	Rated pressure			
							6	6bar			
							10	10bar			
							16	16bar			
							25	25bar			
								Code	Output Signal		
								A P	4 ~ 20mA Pluse		
								R	RS485		
								н	HART		
								<u> </u>	Code	Power Supply	
									0	220VAC	
									1	24VDC	
									2	Battery	
										Code	Others
										Ex	Explosion-proof
										QF	Factory report Other customization
											requirements
Eg:HFM100	S	T.	50	FE	S6	TG	16	APR	1		QF

Transportation and Storage

To prevent the instrument from being damaged during operation, please keep it in the same packaging state as it was shipped from the manufacturer before arriving at the installation site. During storage, the storage location should be indoors with the following conditions:

- 1. Rainproof and moisture-proof.
- 2.Mechanical vibration is small, and impact is avoided.
- 3.Temperature range -20~+60°C, humidity not greater than 80%.

Operation

Carry out the following inspections before putting the flowmeter into operation:

- 1. Whether the flow meter is damaged during transportation and installation.
- 2.Is the power supply voltage used consistent with the nameplate voltage?
- 3. The instrument is correctly wired.

After inspection, open the pipeline valve to fill the pipeline with liquid. Pay attention to eliminate leaks and residual gas in the system. Then turn on the power of the instrument. Generally, the flow meter can work normally after 10 minutes of preheating.

Guarantee and Repair

Dear users:

Thank you for using our products. To make our service more satisfying to you, please read this regulation carefully and properly.

Manage this service warranty card. The service warranty card must be provided under warranty.

- 1. Warranty Description:
- The warranty period of this product is one year, the specific warranty period published on the website shall prevail.
- ②Please consider carefully when you buy it. If there is no quality problem, we will not provide return or exchange service for you.
- 2.Under one of the following circumstances, no matter whether it is within the warranty period, there is no free warranty.
- ①The surface is corroded, cracked or concave and convex caused by human and damaged due to improper installation, use or maintenance.
- ②The delivery period of the product exceeds the warranty period.
- 3 Those repaired by unauthorized service providers or technicians or disassembled and installed by users themselves.
- 3.The Company reserves the right to the final interpretation and change of the terms of Service.