
HPTM180 Combined Pressure & Temperature Transmitter




Nanjing Hangjia Electronic Technology Co.,Ltd.

Overview

HPTM180 Combined Pressure & Temperature Transmitter is an industry leading and unique design with a highly stable pressure sensitive element for independent measurement and a high accuracy temperature sensitive element for accurate measurement of medium pressure and temperature at the same time. The compact size of the transmitter allows for a wide range of pressure and electrical interfaces to be selected, while the unique breathable design for small pressure measurements allows for more stable pressure measurements. The original design of the front temperature sensing element is more advanced than traditional temperature measurement methods and introduces a smaller temperature difference, allowing for a more accurate measurement of the medium temperature.

The product meets the requirements for accurate measurement of multiple parameters at one measurement point and is widely used for simultaneous measurement of pressure and temperature of fluids in industrial process control.

Working principle:



The temperature sensor is a built-in high precision PT100 or PT1000 with a measurement position close to the medium to be measured, a small temperature difference and a fast response. The temperature measurement is also supported by a probe rod structure in order to reach the centre of the temperature to be measured.

The pressure sensor is a highly stable and accurate silicon piezoresistive pressure-sensing core, where the process pressure acts directly on the isolation diaphragm, causing it to deform. The signal conditioning circuit converts the MEMS chip signal into a standard current or voltage output.

Features


- Parallel measurement of temperature and pressure
- Up to class 0.2 pressure channel measurement
- Temperature sensor front measurement for smaller errors
- Breathable design for more stable pressure measurement
- Multiple electrical interfaces supported


Parameters

Pressure Range	-100kPa0~50kPa40MPa[Gauge pressure];				
-	0~50kPa10MPa[Absolute pressure]				
Temperature Range	-40∼100°C				
Measuring Medium	Various liquids, gases and various compatible with contact materials				
Output Signal	Two way 4~20mADC[two-wire];				
	Two ways 0-5VDC[three-wire];				
	Two way 0-10VDC[three-wire];				
	4~20mA[two-wires]+PT100/PT1000[three-wire];				
	Modbus-RTU/RS485[four-wire]				
Accuracy	±0.5%FS (pressure sensor, normal), ±0.2%FS (pressure sensor, customized)				
	±0.4°C (temperature sensor)				
Electrical Connection	DIN43650/ Hirschmann, cable outlet, M12*1				
Long-term Stability	±0.2%FS/year				
Response Time	≤3ms (pressure)				
Start-up Time	≤5s				
*Accuracy according to IEC 60770 (non-	linearity, hysteresis, repeatability)				
Compensation temperature Range	-10∼70°C				
Temperature Coefficient of Zero	±1.5%FS(Reference 30ºC)				
Temperature Coefficient of Full Scale	±1.5%FS(Reference 30ºC)				
Medium Temperature	-40∼100°C				
Ambient Temperature	-40∼85℃				
Storage Temperature	-40~85℃				
Protection grade	IP65, Hirschmann electrical connection				
	IP66, M12 x 1 connector (housing without breathable design)				
	IP67, cable outlet (housing not designed to breathe)				
Electrical Protection	Short circuit protection				
	Reverse polarity protection				
	Electromagnetic compatibility				
Mechanical Stability	Vibration 20g(20~5000Hz)				
	Shock resistance 50g(11ms)				
Insulation resistance	>20MΩ 500VDC				

Dielectric strength <2mA 500VAC 1min

Structure Drawings(Unit:mm)







Note:

- 1. The dimensions listed in the diagram may change with the update of the process.
- 2.RS485 communication, height increase of about 25mm.
- 3. Support the customization of the shape structure with temperature probe rod.

Electrical Connection





Output signal	Pressure: two-w	Temperature: three-wire PT100/PT1000			
	Power supply+(+V) Supply-(0V/+OUT)		А	В	В
Cable outlet	red	black	blue	yellow	green
M12×1	1	2	3	4	5
M12×1, with cable	brown	black	blue	white	grey


Output signal	Pressure∶ two-wir	re 4 ~ 20mA current	Temperature: two-wire 4 ~ 20mA current		
	Power supply+(+V) Power supply-(0V/+OUT)		Power supply+(+V)	Power supply-(0V/+OUT)	
Hirschmann /DIN43650	1	2	3	4	
Cable outlet	red	black	yellow	green	

M12×1	1	2	3	4
M12×1, with cable	brown	black	blue	white

Output signal	Pressure: thr	ee wire voltage	Temperature: three wire voltage		
	Power	Common	Pressure output	Temperature output	
	supply+(+V)	port(GND)	(+OUT)	(+OUT)	
Hirschmann	1	2	2	4	
/DIN43650	1	2	3		
Cable outlet	red	black	yellow	green	
M12×1	1	2	3	4	
M12×1,with cable	brown	black	blue	white	


Output signal	Four-wire Modbus-RTU/RS485					
	Power supply+(+V)	Power supply-(-V)	RS485A	RS485B		
Hirschmann	1	2	3	4		
Cable outlet	red	black	yellow	green		
M12×1			3	4		
M12×1, with cable			blue	white		

Wiring Diagram




Pressure: two-wire 4 to 20mA current

Temperature: two-wire 4 to 20mA current (Hirschmann electrical connection)




Pressure: 3-wire voltage output

Temperature: 3-wire voltage output (Hirschmann electrical connection)



Pressure: 2-wire 4 to 20mA current

Temperature: 3-wire PT100/PT1000 (Direct cable outlet)



4-wire Modbus-RTU/RS485 (Hirschmann Electrical Connection)

Ordering Guide

Model Name	Туре								
	Combined Pressure & Temperature Transmitter								
	Pressure Range								-
	(X1 ~ X2)kPa								
		Temperature							
		(T1 ~ T2)°C							
			Code	Output	Output				
			B1 PT1 00	(4 ~ 20)mA	three-wire PT100				
			B1 PT1 000	(4 ~ 20)mA	three-wire PT 1000				
			B1 B1	(4 ~ 20)mA	(4 ~ 20)mA				
			B3 B3	(0~10)V	(0~10)V				
			B4B4	(0 ~ 5)V	(0 ~ 5)V				
			B7	Modbus-	RTU/RS485				
				Code	Process				
				P1	connection M20×1.5				
			1	G12	G1/2				
				G34	G3/4				
						Electrical			
					Code	connection			
				1	C1	Normal Hirschmann			
					C1.1	Mini-size Hirschmann			
					C2	cable outlet			
					C5	M12×1 -4P			
					C6	M12×1 -5P Code	Pressure		
						54	304		
						56	31 6L		
							Code	Length	
							L	L=Insertion length(mm)	
								Code	Additional functions
								G	Gauge pressure (Default)
								Α	Absolute pressure Other
Ex: HPTM180	(0 ~ 1)MPa	(0 ~ 100) ℃	B1 B1	P1	C1	54	L=50mm		G